



M. Flom Associates, Inc. - Global Compliance Center

3356 North San Marcos Place, Suite 107, Chandler, Arizona 85225-7176

www.mflom.com general@mflom.com (480) 926-3100, FAX: 926-3598

November 15th, 2000

Federal Communications Commission,
Via Electronic Mail

Attention: Andy Leimer
Applicant: TELSON ELECTRONICS CO. LTD.
Equipment: FCC ID: MC6TDC8020
Reference: EA98709 Corr. 16700 October 20. 2000

Andy:

In reply to your abovenoted correspondence, please note:

Item 1. This device does not have a headset or similar output provisions

Attached please find statement from the Applicant (Korea) to this effect. It will also appear in their Manual.

Item 2. (ALSO in reply to Item 3 of previous corresp. 16083)

Dr. Gandhi performed SAR testing for this unit and originally provided the photo of the test setup. He subsequently referred to and supplied the attached IEEE Transactions on Electromagnetic Compatibility article. For your added information, we are attaching a copy of this article as a reply to the Commission's request.

We trust this now answers all the FCC's requests and that a Grant will be forthcoming A.S.A.P.

Personal regards,

MORTON FLOM, P. Eng.

mf;mgf

encs.

cc: Applicant: USA representative

cc: A2LA Corrective Action file