




Test report No. : 4789558396-US-R1-V0
Page : 317 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789558396-US-R1-V0
Page : 318 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT


Ch149



Ch157



Ch165



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Average



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 320 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0



802.11ax (HE40)

Peak









Test report No. : 4789558396-US-R1-V0
Page : 323 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT

Ch102



Ch110



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789558396-US-R1-V0
Page : 324 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT


Ch134



Ch151



Ch159



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 325 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT

Average



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 326 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



802.11ax (HE80)


Peak






Test report No. : 4789558396-US-R1-V0
Page : 328 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT

Ch122



Ch155



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Average






OFDMA

802.11ax (HE20)


Peak






Test report No. : 4789558396-US-R1-V0
Page : 331 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT


Ch52



Ch60



Ch64



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 332 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789558396-US-R1-V0
Page : 333 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT


Ch149



Ch157



Ch165



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Average





Test report No. : 4789558396-US-R1-V0
Page : 335 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0



802.11ax (HE40)

Peak









Test report No. : 4789558396-US-R1-V0
Page : 338 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT

Ch102



Ch110



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789558396-US-R1-V0
Page : 339 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT


Ch134



Ch151



Ch159



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 340 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT

Average



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 341 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



802.11ax (HE80)


Peak






Test report No. : 4789558396-US-R1-V0
Page : 343 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT

Ch122



Ch155




Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Ch42

Horizontal

Data: 142 File: D:\E3 Test Data\Project\Sparklan_4789558396_VINFB-266AX(BT)\5G\Bandedge_OFDMAEM6 (153) Date: 02-03-2021

Level (dBm/1m)

Frequency (MHz)

Vertical

Data: 140 File: D:\E3 Test Data\Project\Sparklan_4789558396_VINFB-266AX(BT)\5G\Bandedge_OFDMAEM6 (153) Date: 02-03-2021

Level (dBm/1m)

Frequency (MHz)

Ch58

Horizontal

Data: 146 File: D:\E3 Test Data\Project\Sparklan_4789558396_VINFB-266AX(BT)\5G\Bandedge_OFDMAEM6 (153) Date: 02-03-2021

Level (dBm/1m)

Frequency (MHz)

Vertical

Data: 144 File: D:\E3 Test Data\Project\Sparklan_4789558396_VINFB-266AX(BT)\5G\Bandedge_OFDMAEM6 (153) Date: 02-03-2021

Level (dBm/1m)


Frequency (MHz)



Appendix II Radiated Spurious Emission Measurement


Non-Beamforming mode

802.11a





Test report No. : 4789558396-US-R1-V0
Page : 346 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 347 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 348 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 349 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 350 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT

OFDM

802.11ax (HE20)



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 351 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 352 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 353 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789558396-US-R1-V0
Page : 354 of 393
Issued date : Mar. 16, 2021
FCC ID : RYK-WNFB266AXIBT



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0