FCC TEST REPORT Report No.: F461101

# **APPENDIX C. Setup Photograph**

**Spurious Conduction** 



#### **FRONT VIEW**




### **REAR VIEW**

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3
Issued Date : June 21, 2004

FCC TEST REPORT Report No. : F461101



### **SIDE VIEW**


#### SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC TEST REPORT Report No.: F461101

# **Spurious Radiation**



#### **FRONT VIEW**



## **REAR VIEW**

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3
Issued Date : June 21, 2004