


Label and location





Control



LAN



HDMI
Input



USB C



HDMI
Output



USB A



Service



Microphone



Microphone



Audio Line Out



Factory Reset



Power Input



IS 13252 (Part 1)/
IEC 60950-1



R-XXXXXXXX
www.bis.gov.in



IFT: XXXXXXyy-yyyy

CMIIT-ID: yyyyXXyyyy

CAN ICES-3(A)/NMB-3(A)

5.2/5.3GHz is limited to
indoor use only in Japan

CONTAINS APPROVED RADIO
MODULE CERTIFIED NUMBER:
201-190982 and R-C-TNY-P3310

RAMATEL X-00000

Complies with
IMDA standards
DB101992

XU101307-18046 모니터
R-R-TNY- XXXyy-yy
전화: +82-2-3429-8000

FCC ID : LDK603202337

IC : 2461N-603202337



cisco-returns.com

2.4 DS/ OF 4

XXXX R-NZ

ANATEL
00658-19-01086



Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134, USA
Designed by Cisco(思科研发 / Conçu par Cisco)
www.cisco.com

Product name (产品名称 / 器材名稱/Nom Du Produit): Cisco Webex Board Pro 75 视频会议终端
Model (型号 / 型號 / Modèle):TTC60-32

Contains FCC ID: LDKNVTX21737 Contains IC: 2461N-NVTX21737

Made in China 中国制造
Fabriqué en Chine
Mfg. site:
Mfg. date / Date de fabrication: DDMMYY

This device complies with Part 15 of the FCC Rules.
Operation is subject to the following two conditions:
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation.

Apparatet må tilkoples jordet stikkontakt. Apparaten
skall anslutas till jordat uttag. Laite on liitettävä
suojakoskettimilla varustettuun pistorasiaan. Apparatets
stikprop skal tilsluttes en stikkontakt med jord, som giver
forbindelse til stikproppens jord.

P/N:



S/N:



COO:



MAC:



PID/VID:



Warning: Shock hazard - Do not open
AVIS: Risque de choc électrique - Ne pas ouvrir
警告: 电击危险-不要打开

Power input (輸入/Entrée):100-240VAC, 4.5-3.5 A, 50/60 Hz