

Appendix C. Set up Photograph Spurious Radiation



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C2 Issued Date : Jan. 12, 2005

Report No.: FG4O1206

Report No. : FG4O1206





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C2 Issued Date : Jan. 12, 2005