Appendix C. Set up Photograph

Conducted Emission

Mode 1



FRONT VIEW




REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C4
Report Issued Date : Jun. 06, 2006
Report Version : Rev. 01

Report No.: FR5D2711





SIDE VIEW

Mode 2~3



FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C4
Report Issued Date : Jun. 06, 2006
Report Version : Rev. 01





REAR VIEW



SIDE VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C4
Report Issued Date : Jun. 06, 2006
Report Version : Rev. 01






Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C4
Report Issued Date : Jun. 06, 2006
Report Version : Rev. 01