

APPENDIX 3: Photographs of test setup

Radiated emission Above 1GHz




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst case position

(Horizontal: X-axis / Vertical: Y-axis) Below 1GHz

(Horizontal: X-axis / Vertical: Z-axis) Above 1GHz

X-axis



Y-axis



Z-axis



UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst case position



Mechanical Key (Not Inserted) Worst



Mechanical Key (Inserted)

End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124