Correspondence by Project

Project Number:

577374205

| Correspondence Number | Memo |
|-----------------------|---|
| EF400129-1 | 1) The block diagram submitted is not sufficient. As per section 2.1033(b)(5) of the FCC rules, the block diagram must show "the frequency of all oscillators used in the device. The signal path and frequency shall be indicated at each block. The tuning range(s) and intermediate frequency(ies) shall be indicated at each block." A new Block Diagram has been submitted. 2) In the documentation provided, it states that the EUT will have a minimum transmission time of two seconds. However, the data provided in the test report shows a transmission of less than one second. Please explain this difference and correct as necessary. A new Operational Description has been submitted. 3) The user manual is missing the required 15.105 statement. Please send a corrected user manual. The product does not contain an independent digital device unrelated to the transmitter operation. |

1 of 1 5/7/2015 10:59 AM