



20MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:29:03

20MHz_Low_16QAM_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:30:06

20MHz_High_QPSK_1@99




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:31:24

20MHz_High_QPSK_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:32:26

20MHz_High_16QAM_1@99



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:33:27

20MHz_High_16QAM_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:34:29

FCC Part 27


B4 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 13:57:46

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 13:58:12

1.4MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 13:58:37

1.4MHz_Low_16QAM_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 13:59:02

1.4MHz_High_QPSK_1@5




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 13:59:40

1.4MHz_High_QPSK_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:00:05

1.4MHz_High_16QAM_1@5




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:00:31

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:00:56

3MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:02:13

3MHz_Low_QPSK_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:02:42

3MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:03:12

3MHz_Low_16QAM_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:03:41

3MHz_High_QPSK_1@14




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:04:24

3MHz_High_QPSK_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:04:54

3MHz_High_16QAM_1@14




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:05:23

3MHz_High_16QAM_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:05:53

5MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:20:48

5MHz_Low_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:07:36

5MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:21:15

5MHz_Low_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:21:42

5MHz_High_QPSK_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:09:11

5MHz_High_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:09:39

5MHz_High_16QAM_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:10:06

5MHz_High_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:10:33

10MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:11:57

10MHz_Low_QPSK_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:12:35

10MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:13:13

10MHz_Low_16QAM_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:13:50

10MHz_High_QPSK_1@49




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:14:40

10MHz_High_QPSK_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:15:17

10MHz_High_16QAM_1@49




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:23:08

10MHz_High_16QAM_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:24:25

15MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:26:03

15MHz_Low_QPSK_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:26:53

15MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:27:41

15MHz_Low_16QAM_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:28:31

15MHz_High_QPSK_1@74




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:29:34

15MHz_High_QPSK_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:30:25

15MHz_High_16QAM_1@74




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:31:14

15MHz_High_16QAM_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:32:04

20MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:33:51

20MHz_Low_QPSK_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:34:53

20MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:35:53

20MHz_Low_16QAM_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:36:55

20MHz_High_QPSK_1@99




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:38:09

20MHz_High_QPSK_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:39:10

20MHz_High_16QAM_1@99



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:40:09


20MHz_High_16QAM_100@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:41:11


B7 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:42:11

5MHz_Low_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:42:18

5MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:42:34

5MHz_Low_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:42:50

5MHz_High_QPSK_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:43:20

5MHz_High_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:43:36

5MHz_High_16QAM_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:43:51

5MHz_High_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:44:07

10MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:45:13

10MHz_Low_QPSK_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:45:29

10MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:45:45

10MHz_Low_16QAM_50@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:46:01


10MHz_High_QPSK_1@49



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 10.NOV.2024 14:46:31


10MHz_High_QPSK_50@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 10.NOV.2024 14:46:47


10MHz_High_16QAM_1@49



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 10.NOV.2024 14:47:03


10MHz_High_16QAM_50@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 10.NOV.2024 14:47:35


15MHz_Low_QPSK_1@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 10.NOV.2024 14:48:50


15MHz_Low_QPSK_75@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang


Date: 10.NOV.2024 14:49:09

15MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:49:27

15MHz_Low_16QAM_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:49:46

15MHz_High_QPSK_1@74




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:50:19

15MHz_High_QPSK_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:50:38

15MHz_High_16QAM_1@74




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:50:55

15MHz_High_16QAM_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:51:16

20MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:52:23

20MHz_Low_QPSK_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:52:43

20MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:53:01

20MHz_Low_16QAM_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:53:22

20MHz_High_QPSK_1@99




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:53:57

20MHz_High_QPSK_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 14:54:17

20MHz_High_16QAM_1@99



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:54:35


20MHz_High_16QAM_100@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 14:54:56


B12, Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:40:34

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:11:14

1.4MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:41:55

1.4MHz_Low_16QAM_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:12:35

1.4MHz_High_QPSK_1@5




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:43:30

1.4MHz_High_QPSK_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:44:26

1.4MHz_High_16QAM_1@5




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:45:07

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:54:47

3MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:47:15

3MHz_Low_QPSK_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:48:00

3MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:48:45

3MHz_Low_16QAM_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:9:30

3MHz_High_QPSK_1@14




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:50:25

3MHz_High_QPSK_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:1:13

3MHz_High_16QAM_1@14




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:51:56

3MHz_High_16QAM_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:12:42

5MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:54:23

5MHz_Low_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:55:14

5MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:56:05

5MHz_Low_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:16:55

5MHz_High_QPSK_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:57:56

5MHz_High_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 22:18:48

5MHz_High_16QAM_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 22:59:36

5MHz_High_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:00:28

10MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:02:23

10MHz_Low_QPSK_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:03:24

10MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:04:25

10MHz_Low_16QAM_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:05:27

10MHz_High_QPSK_1@49




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:06:40

10MHz_High_QPSK_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:07:41

10MHz_High_16QAM_1@49



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:08:42


10MHz_High_16QAM_50@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:10:43


B13, Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:12:02

5MHz_Low_QPSK_25@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:12:34


5MHz_Low_16QAM_1@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:13:05


5MHz_Low_16QAM_25@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:13:36


5MHz_High_QPSK_1@24



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:14:32


5MHz_High_QPSK_25@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:15:04


5MHz_High_16QAM_1@24



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:15:35


5MHz_High_16QAM_25@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:16:07


10MHz_Middle_QPSK_1@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:17:40


10MHz_Middle_QPSK_1@49



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:18:12


10MHz_Middle_QPSK_50@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:18:43


10MHz_Middle_16QAM_1@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:19:15


10MHz_Middle_16QAM_1@49



ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:19:46

10MHz_Middle_16QAM_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang

Date: 8.NOV.2024 23:20:49


B17 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:22:21

5MHz_Low_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:23:13

5MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:24:03

5MHz_Low_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:24:54

5MHz_High_QPSK_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:25:56

5MHz_High_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:26:48

5MHz_High_16QAM_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:27:35

5MHz_High_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:18:28

10MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:30:10

10MHz_Low_QPSK_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:11:11

10MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:32:13

10MHz_Low_16QAM_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:33:15

10MHz_High_QPSK_1@49




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:34:25

10MHz_High_QPSK_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:55:30

10MHz_High_16QAM_1@49



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:36:31


10MHz_High_16QAM_50@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 23:18:33


B66 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:36:17

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:36:43

1.4MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:37:10

1.4MHz_Low_16QAM_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:37:36

1.4MHz_High_QPSK_1@5




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:38:15

1.4MHz_High_QPSK_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:38:42

1.4MHz_High_16QAM_1@5




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:39:06

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:39:32

3MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:41:31

3MHz_Low_QPSK_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:42:00

3MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:42:30

3MHz_Low_16QAM_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:42:59

3MHz_High_QPSK_1@14




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:43:43

3MHz_High_QPSK_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:44:13

3MHz_High_16QAM_1@14




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:44:43

3MHz_High_16QAM_15@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:45:13

5MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:47:13

5MHz_Low_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:47:42

5MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:48:12

5MHz_Low_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:48:40

5MHz_High_QPSK_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:49:24

5MHz_High_QPSK_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:49:53

5MHz_High_16QAM_1@24




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:50:21

5MHz_High_16QAM_25@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:50:51

10MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:53:44

10MHz_Low_QPSK_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 15:54:24

10MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:55:04

10MHz_Low_16QAM_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:55:43

10MHz_High_QPSK_1@49




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:56:27

10MHz_High_QPSK_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:57:16

10MHz_High_16QAM_1@49




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:57:55

10MHz_High_16QAM_50@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 15:59:14

15MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:01:33

15MHz_Low_QPSK_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:02:24

15MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:03:14

15MHz_Low_16QAM_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:04:05

15MHz_High_QPSK_1@74




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:05:09

15MHz_High_QPSK_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:06:00

15MHz_High_16QAM_1@74




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:06:49

15MHz_High_16QAM_75@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:07:40

20MHz_Low_QPSK_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:10:16

20MHz_Low_QPSK_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:11:17

20MHz_Low_16QAM_1@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:12:18

20MHz_Low_16QAM_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:13:19

20MHz_High_QPSK_1@99




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:14:35

20MHz_High_QPSK_100@0




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:15:36

20MHz_High_16QAM_1@99



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:16:27

20MHz_High_16QAM_100@0



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:17:39


Spurious Emissions at Antenna Terminal

FCC For 90S

B26_1 , Normal


1RB was the worst case

1_1.4MHz_Low_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:33:23

1_1.4MHz_High_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:34:12

1_3MHz_Low_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:35:03

1_3MHz_High_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:35:52

1_5MHz_Low_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:36:46

1_5MHz_High_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:37:35

1_10MHz_Low_QPSK_1@0(30MHz~9.24GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:38:27


1_15MHz_Low_QPSK_1@0(30MHz~9.24GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:39:53


B26_3 , Normal
1RB was the worst case

3_1.4MHz_Middle_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:56:01

3_3MHz_Middle_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:57:00

3_5MHz_Middle_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:57:53

3_10MHz_Middle_QPSK_1@0(30MHz~9.24GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 8.NOV.2024 21:58:46

3_15MHz_Middle_QPSK_1@0(30MHz~9.24GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:59:41

FCC Part 22H


B5 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 20:57:34

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 20:58:21

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 20:59:08

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:00:20

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:01:05

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:01:51

5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:03:14

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:04:01

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:04:47

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:05:59

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:06:47


10MHz_High_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:07:34


B26_2 , Normal
1RB was the worst case

2_1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:41:00

2_1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:41:46

2_1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:42:32

2_3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:43:52

2_3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:44:39

2_3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:45:27

2_5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:46:44

2_5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:47:37

2_5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:48:29

2_10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:50:02

2_10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:50:55

2_10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:51:47

2_15MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:53:10

2_15MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:54:05

2_15MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:55:01

FCC Part 24E

B2 , Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:30:56

1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:31:19

1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:31:42

3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:33:18

3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:33:41

3MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:34:04

5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:36:16

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:36:39

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:37:02

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:39:14

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:39:37

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:40:01

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:41:40

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:42:04

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:42:29

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:44:13

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:44:39

20MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
 Date: 10.NOV.2024 16:45:05

B25 , Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:11:44

1.4MHz_Middle_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:12:08

1.4MHz_High_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:12:32

3MHz_Low_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:14:18

3MHz_Middle_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:14:43

3MHz_High_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:15:08

5MHz_Low_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:16:48

5MHz_Middle_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:17:12

5MHz_High_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:17:37

10MHz_Low_QPSK_1@0(30MHz~20.15GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:19:35

10MHz_Middle_QPSK_1@0(30MHz~20.15GHz)









ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:19:59

10MHz_High_QPSK_1@0(30MHz~20.15GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:20:23




FCC Part 27

B4 , Normal


1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:46:26

1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:46:49

1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:47:13

3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:49:10

3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:49:34

3MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:49:57

5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:51:35

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:51:58

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:52:22

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:53:57

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:54:20


10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:54:43




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:56:39




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:57:04




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:57:29



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:59:07




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:59:32



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 16:59:56


B7 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:01:25

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:01:50

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:02:16

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:03:55

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:04:21

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:04:46

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:06:36

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:07:03

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:07:30

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:09:23

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:09:50


20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 10.NOV.2024 17:10:17


B12 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:06:41

1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:09:28

1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:10:13

3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:11:32

3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:12:19

3MHz_High_QPSK_1@0(30MHz~8.16GHz)



ProjectNo.:2402Y37628E-RF Tester:Karl Liang
Date: 8.NOV.2024 21:13:07