



n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB1@0 -47.65dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:40:15

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB1@77 -47.79dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:41:15

n78_2_30MHz_30kHz_3685MHz_DFT-s-OFDM
QPSK_RB75@0 -45.86dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:42:13

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB100@0 -46.90dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:45:17

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@0 -47.08dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:43:20

n78_2_40MHz_30kHz_3570MHz_DFT-s-OFDM
QPSK_RB1@105 -46.97dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:44:20

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 -47.40dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:48:19

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.43dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:46:22

n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@105 -47.13dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:47:21

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB100@0 -47.52dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:51:30

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@0 -47.74dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:49:31

n78_2_40MHz_30kHz_3680MHz_DFT-s-OFDM
QPSK_RB1@105 -47.09dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:50:32

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB128@0 -44.64dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:54:38

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@0 -47.57dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:52:39

n78_2_50MHz_30kHz_3575MHz_DFT-s-OFDM
QPSK_RB1@132 -47.14dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:53:39

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB128@0 -47.36dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:57:44

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.16dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:55:44

n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@132 -47.22dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:56:44

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB128@0 -47.48dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:05:12

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@0 -47.33dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:03:25

n78_2_50MHz_30kHz_3675MHz_DFT-s-OFDM
QPSK_RB1@132 -47.38dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:04:18

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB162@0 -47.39dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:08:03

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@0 -47.64dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:06:15

n78_2_60MHz_30kHz_3580MHz_DFT-s-OFDM
QPSK_RB1@161 -47.66dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:07:10

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB162@0 -47.45dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:11:02

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.91dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:09:10

n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@161 -47.45dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:10:07

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB162@0 -47.45dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:13:49

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@0 -47.20dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:12:01

n78_2_60MHz_30kHz_3670MHz_DFT-s-OFDM
QPSK_RB1@161 -47.41dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:12:56

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB180@0 -44.21dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:16:45

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@0 -46.91dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:14:52

n78_2_70MHz_30kHz_3585MHz_DFT-s-OFDM
QPSK_RB1@188 -47.81dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:15:47

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -47.35dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:19:39

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -46.19dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:17:50

n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -47.12dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:18:44

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -47.39dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:22:36

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@0 -47.51dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:20:47

n78_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -47.81dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:21:42

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@0 -47.61dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:23:43

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -47.04dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:24:39

n78_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -47.34dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 13:25:32

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.15dBm




ProjectNo.:2401Z104805E-RF Testert:Rungfunaster Liang
Date: 16.DEC.2024 08:59:15

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -47.38dBm




ProjectNo.:2401Z104805E-RF Testert:Rungfunaster Liang
Date: 16.DEC.2024 09:00:14

n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -47.46dBm




ProjectNo.:2401Z104805E-RF Testert:Rungfunaster Liang
Date: 16.DEC.2024 09:01:05

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@0 -47.63dBm




ProjectNo.:2401Z104805E-RF Testert:Rungfunaster Liang
Date: 16.DEC.2024 09:02:11

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -47.07dBm




ProjectNo.:2401Z104805E-RF Testert:Rungfunaster Liang
Date: 16.DEC.2024 09:03:06

n78_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -47.30dBm




ProjectNo.:2401Z104805E-RF Testert:Rungfunaster Liang
Date: 16.DEC.2024 09:04:01


n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@0 -47.49dBm




n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -47.18dBm




n78_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -47.26dBm




n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.05dBm




n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -47.36dBm




n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -47.17dBm




n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@0 -46.77dBm




n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -45.58dBm




n78_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -47.45dBm




n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@0 -47.18dBm




n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -44.30dBm




n78_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -47.01dBm




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.46dBm




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -47.62dBm




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -47.45dBm



n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@0 -47.57dBm



n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -44.55dBm



n78_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -47.05dBm

