


INTERTEK TESTING SERVICE

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)


Model: GMR4055-2CKHS, GMR4060-2CKHS



INTERTEK TESTING SERVICE

Configuration Photographs Worst-Case Radiated Emissions (Rear View)

Model: GMR4055-2CKHS, GMR4060-2CKHS



INTERTEK TESTING SERVICE

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)


Model: GMR4055-2CKHS, GMR4060-2CKHS



INTERTEK TESTING SERVICE

Configuration Photographs Worst-Case Radiated Emissions (Rear View)


Model: GMR4055-2CKHS, GMR4060-2CKHS



INTERTEK TESTING SERVICE

Configuration Photographs Worst-Case Line-Conducted Emissions (Front View)

Model: GMR4055-2CKHS, GMR4060-2CKHS




INTERTEK TESTING SERVICE

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Rear View)

Model: GMR4055-2CKHS, GMR4060-2CKHS



INTERTEK TESTING SERVICE

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Side View)

Model: GMR4055-2CKHS, GMR4060-2CKHS

