





## Duty Cycle NVNT n20 5580MHz Ant0



## Duty Cycle NVNT n20 5700MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



## Duty Cycle NVNT n40 5510MHz Ant0



## Duty Cycle NVNT n40 5550MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



## Duty Cycle NVNT n40 5670MHz Ant0




## Duty Cycle NVNT ac20 5500MHz Ant0






## Duty Cycle NVNT ac20 5580MHz Ant0



## Duty Cycle NVNT ac20 5700MHz Ant0



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



## Duty Cycle NVNT ac40 5510MHz Ant0



## Duty Cycle NVNT ac40 5550MHz Ant0




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity






## Duty Cycle NVNT ax20 5580MHz Ant0




## Duty Cycle NVNT ax20 5700MHz Ant0






## Duty Cycle NVNT ax40 5510MHz Ant0



## Duty Cycle NVNT ax40 5550MHz Ant0




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity





| Condition | Mode | Frequency (MHz) | Antenna | Duty Cycle (%) | Correction Factor (dB) | 1/T (kHz) |
|-----------|------|-----------------|---------|----------------|------------------------|-----------|
| NVNT      | a    | 5500            | Ant1    | 94.56          | 0.24                   | 0.91      |
| NVNT      | a    | 5580            | Ant1    | 94.56          | 0.24                   | 0.91      |
| NVNT      | a    | 5700            | Ant1    | 94.65          | 0.24                   | 0.91      |
| NVNT      | n20  | 5500            | Ant1    | 97.29          | 0.12                   | 0.44      |
| NVNT      | n20  | 5580            | Ant1    | 97.33          | 0.12                   | 0.44      |
| NVNT      | n20  | 5700            | Ant1    | 97.29          | 0.12                   | 0.44      |
| NVNT      | n40  | 5510            | Ant1    | 97.23          | 0.12                   | 0.46      |
| NVNT      | n40  | 5550            | Ant1    | 97.23          | 0.12                   | 0.46      |
| NVNT      | n40  | 5670            | Ant1    | 97.23          | 0.12                   | 0.46      |
| NVNT      | ac20 | 5500            | Ant1    | 97.34          | 0.12                   | 0.44      |
| NVNT      | ac20 | 5580            | Ant1    | 97.3           | 0.12                   | 0.44      |
| NVNT      | ac20 | 5700            | Ant1    | 97.34          | 0.12                   | 0.44      |
| NVNT      | ac40 | 5510            | Ant1    | 97.19          | 0.12                   | 0.46      |
| NVNT      | ac40 | 5550            | Ant1    | 97.19          | 0.12                   | 0.46      |
| NVNT      | ac40 | 5670            | Ant1    | 97.19          | 0.12                   | 0.46      |
| NVNT      | ax20 | 5500            | Ant1    | 97.34          | 0.12                   | 0.44      |
| NVNT      | ax20 | 5580            | Ant1    | 97.34          | 0.12                   | 0.44      |
| NVNT      | ax20 | 5700            | Ant1    | 97.34          | 0.12                   | 0.44      |
| NVNT      | ax40 | 5510            | Ant1    | 97.19          | 0.12                   | 0.46      |
| NVNT      | ax40 | 5550            | Ant1    | 97.19          | 0.12                   | 0.46      |
| NVNT      | ax40 | 5670            | Ant1    | 97.24          | 0.12                   | 0.46      |



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




## Test Graphs

## Duty Cycle NVNT a 5500MHz Ant1




## Duty Cycle NVNT a 5580MHz Ant1






## Duty Cycle NVNT a 5700MHz Ant1




## Duty Cycle NVNT n20 5500MHz Ant1






## Duty Cycle NVNT n20 5580MHz Ant1




## Duty Cycle NVNT n20 5700MHz Ant1






## Duty Cycle NVNT n40 5510MHz Ant1



## Duty Cycle NVNT n40 5550MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



## Duty Cycle NVNT n40 5670MHz Ant1



## Duty Cycle NVNT ac20 5500MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



## Duty Cycle NVNT ac20 5580MHz Ant1



## Duty Cycle NVNT ac20 5700MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



## Duty Cycle NVNT ac40 5510MHz Ant1



## Duty Cycle NVNT ac40 5550MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity






## Duty Cycle NVNT ax20 5580MHz Ant1




## Duty Cycle NVNT ax20 5700MHz Ant1






## Duty Cycle NVNT ax40 5510MHz Ant1



## Duty Cycle NVNT ax40 5550MHz Ant1




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A &amp; 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity