DW-H5600_CW3516 Display of certificate number



- ① Instructions for Label display are provided in the user manual for the entire product.
- ② This device does not require special accessories or supplemental plug-ins to access the information"



- 1. Hold down S2 for about 2 seconds will changes to setting mode and "SETTING" is displayed.
- 2. Press S2 and select "REGULATORY" by S3.
 - **** Press S3 to "REGULATORY" by 3 times.**
- 3. Press S2, the certificate number will be displayed. The screen changes with S2 or S3.
- **%Press S1** to return to the previous screen.