

APPENDIX 3: Photographs of test setup

Conducted Emission

Slot in




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Conducted Emission
External connect




Photo 1




Photo 2

Radiated Spurious Emission
Slot in (Below 1GHz)




Photo 1




Photo 2

Radiated Spurious Emission
External connect (Below 1GHz)




Photo 1




Photo 2

UL Japan, Inc.
Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission
(Above 1GHz)




Photo 1




Photo 2

Worst Case Position

30-300MHz (External: Horizontal: X-1-axis / Vertical: X-1-axis)

300-1000MHz (Slot in: Horizontal: X-axis / Vertical: X-axis)

Above 1GHz (External: Horizontal: Z-2-axis / Vertical: X-2-axis)

X-1-axis



Y-1-axis



X-2-axis




Y-2-axis



X-3-axis



Y-3-axis



UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

Z-1-axis



X-axis




Z-2-axis



Y-axis



Z-3-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124