

6660-B Dobbin Road Columbia, MD 21045 USA

Tel. 410.290.6652 Fax. 410.290.6654 http://www.pctestlab.com

November 4, 2005

Federal Communications Commission Equipment Approval Services 7435 Oakland Mills Road Columbia, MD 21046 Attn: Mr. Steven Dayhoff

> SUBJECT: Panasonic Corporation of North America FCC ID: ACJ9TGCF-P21 731 Confirmation No.: TC906878 Correspondence Reference No.: 29729 Request for Tech. Info.: 10/05/2005

Dear Steven:

Transmitted herewith, on behalf of **Panasonic Corporation of North America** is an amendment provided in response to the request for technical information dated October 5, 2005.

- Please find attached two Simultaneous Transmission Profiles. The first one shows the 850 MHz GSM band hot spot with the BT and WLAN transmitter SAR hot spots superimposed. The second profile shows the PCS GSM band hot spot with the BT and WLAN hot spots superimposed. These profiles show that there is no overlap of the hot spots.
- 2. New SAR measurement data (properly re-evaluated) replacing the plots in question are attached.
- 3. Please find the attached new body 850 MHz band SAR measurement data replacing the plot in question.
- 4. We have an Agilent E4432B GPRS/GSM signal generator. With this instrument we can generate single and multi-slot signals with equal amplitude. A test with both single slot and two slot signals of equal amplitudes driving a dipole is attached. The SAR doubles in the two slot configuration in both bands.
- 5. BT-On test results for 850/1900 MHz body SAR are attached.
- 6. The schematics, block diagram and operational description are attached

We trust this information is sufficient to resolve FCC questions in this application. If you have any further questions, please do not hesitate to contact us.

indy Orlanez

cc: Richard Mullen; Panasonic Corporation of North America