



### **APPENDIX 3: Photographs of test setup**

#### **Radiated Spurious Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

### **Worst Case Position**

#### **WLAN**

Below 1GHz (Horizontal: X-axis/ Vertical:Y-axis)


Above 1GHz (Horizontal: X-axis/ Vertical:Y-axis)

#### **BT LE**


Below 1GHz (Horizontal: X-axis/ Vertical:X-axis)

Above 1GHz (Horizontal: X-axis/ Vertical:Y-axis)


#### **X-axis**



#### **Y-axis**



#### **Z-axis**



**End of Report**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124