

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


Worst Case Position

Ant


Below30MHz: X-axis

Above30MHz Hori:X / Vert:X


X-axis



Y-axis



Z-axis



UL Japan, Inc.

Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


Worst Case Position
With transponder / Without transponder

With transponder



transponder

Without transponder (Worst)



*** With transponder: lighting**
Without transponder: flashing

End of Report