Johnson Controls, Inc. Automotive Systems Group One Prince Center Holland, MI 49423



July 30, 2003

Federal Communication Commission Equipment Approval Services, P.O. Box 358315 Pittsburgh, PA 15251-5315 Attention: Authorization & Evaluation Division

RE: Application for Vehicle Level Certification of Johnson Controls Transmitter under 47 CFR 15.231. FCC ID: ACTLHL3

To whom it may concern,

Submitted here are materials for your consideration in determining the grant of certification for a Class II permissive change to the Johnson Controls Interior, LLC, Universal Garage Door Opener product. The FCC ID for this product is CB2ACTLHL3. The change being requested is a "vehicle level" Class II certification, negotiated by the Prince Corporation (later acquired by Johnson Controls Interiors) of Holland, MI. Correspondence between Prince Corporations and the FCC in regard to this testing methodology. A copy of the correspondence regarding this method and a summary of the procedure are available in the attachment "vehicle level.pdf".

As stated in the original grant (Form 731 confirmation #0200587F), the JCI Model CB2ACTLHL3 is part of the Homelink ® III series. Homelink ® III devices are capable of learning garage door opener frequencies and codes from the user's original transmitter. The device is capable of learning in the range between 288MHz and 420MHz excluding forbidden frequency regions.

Johnson Controls Interiors has invested considerable resources into developing our Homelink ® products. For this reason we respectfully request that the following items be held as confidential.

- Circuit Block Diagrams
- Theory of Operation
- Schematics

The Federal Communications Commission will be notified, in writing of any changes in the software/programming of this device that could affect its RF characteristics.

A table of contents for all submitted materials can be found at the end of this letter.

Please do not hesitate to contact me with any questions you may have regarding this report. As always we look forward to your timely response.

Sincerely,

Jeremy P. Bos

RF Test Site Manager Johnson Controls Interiors.

Tel: (616)394-6076/Fax: (616)394-6100

Email: <u>Jeremy.bos@jci.com</u>

July 30, 2003 #EA504983

## **Table of Contents**

1.	General Information	2
	1.1. Product Description	2
	1.2. Related Grants	2
	1.3. Test Methodology	2
	1.4. Test Facility	3
2.	Product Labeling	
	2.1. Label Drawing and Location on Product	3
3.	Test Configuration	
4.	Block Diagram	
5.	Test Setup Photographs	
6.	Conducted Emissions Measurements	
7.	Radiated Emissions Data	
	7.1. Summary of Results	
	7.2. Test Equipment Used	
	7.3. Test Equipment Setup and Procedure	
	7.4. Measured Data	
	7.4.1. Measurements of Fundamentals and Harmonics	
	7.4.1.1. (Table) DUT Tuned to 288MHz (Fundamental)	
	7.4.1.2. (Table) DUT Tuned to 310MHz (Fundamental)	
	7.4.1.3. (Table) DUT Tuned to 418MHz (Fundamental)	
	7.4.1.4. (Table) 288MHz (Harmonics)	
	7.4.1.5. (Table) 310MHz (Harmonics)	
	7.4.1.6. (Table) 418MHz (Harmonics)	
	7.4.1.7. (Table) 390 MHz Fundamental (in vehicle)	
	7.4.1.8. (Table) 390 MHz Fundamental (on table)	
	7.4.1.9. (Table) 390 MHz Harmonics	
	7.4.2. Pulsed Operation	
	7.4.2.1. (Figure) 30% Duty Cycle	
	7.4.2.2. (Figure) 50% Duty Cycle	
	7.4.2.3. (Figure) 80% Duty Cycle	
	7.4.3. Occupied Bandwidth	
	7.4.3.1. (Table) Occupied Bandwidth Measurements	
	7.4.3.2. (Figure) Example of Occupied Bandwidth measurement	
	7.4.4. Emission Spectrum	
	7.4.4.1. (Figure) 288 MHz	
	7.4.4.2. (Figure) 310 MHz	
	7.4.4.3. (Figure) 418 MHz.	
	7.4.4.4. Summary of Emissions Measurements Taken on OATS	
	7.4.5. Variation of Supply Voltage	
	7.4.5.1. (Figure) Plot of output power over supply voltage	
	7.4.5.1. (Table) Output power as a function of supply voltage	
	7.4.6. Verification of Non-Operation in Restricted Bands	
	7.4.7. Verification of De-activation after 5 seconds	
	7.4.7. Verification of De-activation after 5 seconds	
	7.4.8.1. (Figure) Coarse Tuning Pulse (288MHz)	16
	7.4.8.2. Fine Tuning Pulse (288MHz)	
	7.4.8.3. Coarse Tuning Pulse (310MHz)	
	7.4.8.4. Fine Tuning Pulse (310MHz)	
	7.4.8.5. Coarse Tuning Pulse (418 MHz)	
	7.4.8.6. Fine Tuning Pulse (418MHz)	
	7.4.8.7. Summary of Tuning Pulse Measurements	10
	7.5. Formulas and Sample Calculations	
	7.5.1. Adjustment to account for duty cycle	
	7.5.1. Adjustment to account for duty cycle	
	1.3.2. Calculation of FCC IIIIII 13.231	∠∪

July 30, 2003 #EA504983

8.	Photos of Product Tested
	8.1. Front View
	Please refer to attachment named "front_view.jpg"
	8.2. Rear View
	Please refer to attachment named "rear_view.jpg"
	8.3. Unit Disassembled
	Please refer to attachment named "d_assym.jpg"
	8.4. Light Board
	Please refer to attachment named "light_front.jpg"
	Please refer to attachment named "light_back.jpg"
	8.5. Homelink Accessory Board
	Please refer to attachment named "hl3_front.jpg"
	Please refer to attachment named "hl3_back.jpg"
9.	Other Attachments and Description21
	9.1. User Manual
	Please refer to attachment "user_manual.pdf"
	9.2. Schematics/ Tuning Information
	For schematics please refer to attachment "schematics.pdf"
	For tuning information please refer to attachment "tuning.pdf"
	9.3. Theory of Operation
	For schematics please refer to attachment "theory, on pdf"

FCC ID: CB2ACTLHL3