

## 7535 Irvine Center Drive, Suite 100, Irvine, CA 92618 USA TEL: +1 (949) 453-3990 FAX: +1 (949) 453-3995

### DFS client device channel plan and software operational declaration

Date: 2021-12-07

We,Lantronix, Inc., declare that the device, FCC ID: R68OQ660US Model Name: Open-Q 660 uSOM, does not have Ad Hoc on "non-US frequencies" and/or on "DFS frequencies". Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

#### Below is the channel / frequency plan for the device

	СН	1	2	3	4	5	6	7	8	9	10	11
Frequ	ency (MHz)	2412	2417	2422	2427	2432	2437	2442	2447	2452	2457	2462
Sca	an Type	Active	Active	Active	Active	T		Active	Active	Active	Active	Active

#### 5G band 1

	СН	36	38	40	42	44	46	48			
I	Frequency (MHz)	5180	5190	5200	5210	5220	5230	5240			
	Scan Type	Active			1						

#### 5G band 2

СН	52	54	56	58	60	62	64
Frequency (MHz)	5260	5270	5280	5290	5300	5310	5320
Scan Type	Passive		Passive	<b>Passive</b>	Passive	Passive	<b>Passive</b>

#### 5G band 3

СН	100	102	104	106	108	110	112	116		
Frequency (MHz)	5500	5510	5520	5530	5540	5550	5560	5580		
Scan Type	Passive									
CH	132	134	136	138	140	142	144			
Frequency (MHz)	5660	5670	5680	5690	5700	5710	5720			
Scan Type	Passive									

#### 5G band 4

CH	149	151	153	155	157	159	161	165
Frequency (MHz)	5745	5755	5765	5775	5785	5795	5805	5825
Scan Type	Active							

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by a special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before firmware upgrade. Unauthorized modification to firmware will lead to the failure of verification and thus firmware upgrade will not be allowed. Sincerely yours,



# 7535 Irvine Center Drive, Suite 100, Irvine, CA 92618 USA TEL: +1 (949) 453-3990 FAX: +1 (949) 453-3995

Name: Fathi Hakam / Title: VP of Engineering

Tel: +1 (949) 453-3990 Fax: +1 (949) 453-3995

E-mail: fhakam@lantronix.com