



JBP TEST SETUP PHOTOS

1 Radiated Field Strength Measurement




30 MHz-1 GHz (USB Test Mode)



Above 1 GHz (USB Test Mode)



30 MHz-1 GHz (Camera Test Mode)



1 GHz-6 GHz (Camera Test Mode)

2 Conducted Emission



USB Test Mode



Camera test mode