

Date: 09/09/2022

Subject : Request to change in Identification.

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by Repairify, Inc. will establish a new FCC ID: 2A8NIACCNT under Repairify, Inc. code for purpose of marketing. The original grant to Original Applicant will remain in effect.

Per 2.933(b)

1. The original identification is FCC ID: XUJS4001
2. The original grant date is 03/17/2021
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

Sincerely,

Yuri Radzik
Yuri Radzik

Director of Special Projects

Repairify, Inc.

5700 Tennyson Parkway, Suite 600, Plano, TX 75024