



Freq. Stability 20C 2.81V ax40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 01:10:31

Freq. Stability 20C 3.3V ax40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 01:12:03

Freq. Stability 20C 3.80V ax40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 01:10:37

Freq. Stability -20C 3.3V ax40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 01:11:11

Freq. Stability -10C 3.3V ax40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 01:11:24

Freq. Stability 0C 3.3V ax40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 01:11:37

Freq. Stability 10C 3.3V ax40 5755MHz Ant2 0 Minutes




Date: 23.9.2023 01:11:50

Freq. Stability 30C 3.3V ax40 5755MHz Ant2 0 Minutes




Date: 23.9.2023 01:12:16

Freq. Stability 40C 3.3V ax40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 01:12:30

Freq. Stability 50C 3.3V ax40 5755MHz Ant2 0 Minutes




Date: 23.09.2023 01:12:43


Freq. Stability 20C 2.81V ax40 5795MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V ax40 5795MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V ax40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 01:16:35

Freq. Stability -20C 3.3V ax40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 01:16:48

Freq. Stability -10C 3.3V ax40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 01:17:01

Freq. Stability 0C 3.3V ax40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 01:17:14

Freq. Stability 10C 3.3V ax40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 01:17:27

Freq. Stability 30C 3.3V ax40 5795MHz Ant2 0 Minutes




Date: 23.09.2023 01:17:54


Freq. Stability 40C 3.3V ax40 5795MHz Ant2 0 Minutes



Freq. Stability 50C 3.3V ax40 5795MHz Ant2 0 Minutes




Freq. Stability 20C 2.81V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:37:45

Freq. Stability 20C 3.3V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:42:39

Freq. Stability 20C 3.80V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:39:09

Freq. Stability -20C 3.3V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:39:51

Freq. Stability -10C 3.3V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:40:33

Freq. Stability 0C 3.3V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:41:15

Freq. Stability 10C 3.3V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:41:37

Freq. Stability 30C 3.3V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:43:22

Freq. Stability 40C 3.3V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:44:04

Freq. Stability 50C 3.3V ax80 5210MHz Ant1 0 Minutes




Date: 20.09.2023 08:44:46

Freq. Stability 20C 2.81V ax80 5290MHz Ant1 0 Minutes



Freq. Stability 20C 3.3V ax80 5290MHz Ant1 0 Minutes




Freq. Stability 20C 3.80V ax80 5290MHz Ant1 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.91 dB RBW 10 kHz
 Att 30 dB SWT 160 ms VBW 30 kHz Mode Sweep
 SGL Count 40/40

1Pk Max



Marker

Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1	1		5.29 GHz	-42.74 dBm		
M2	1		5.25096 GHz	-27.25 dBm		
M3	1		5.32904 GHz	-28.63 dBm		


Date: 23.07.2023 05:23:00

Freq. Stability -20C 3.3V ax80 5290MHz Ant1 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.91 dB RBW 10 kHz
 Att 30 dB SWT 160 ms VBW 30 kHz Mode Sweep
 SGL Count 40/40

1Pk Max




Marker

Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1	1		5.29 GHz	-37.31 dBm		
M2	1		5.25096 GHz	-27.21 dBm		
M3	1		5.32904 GHz	-26.63 dBm		


Date: 23.07.2023 05:23:35

Freq. Stability -10C 3.3V ax80 5290MHz Ant1 0 Minutes




Date: 23.09.2023 05:24:09

Freq. Stability 0C 3.3V ax80 5290MHz Ant1 0 Minutes




Date: 23.09.2023 05:24:43

Freq. Stability 10C 3.3V ax80 5290MHz Ant1 0 Minutes




Date: 23.9.2023 05:25:17

Freq. Stability 30C 3.3V ax80 5290MHz Ant1 0 Minutes




Date: 23.9.2023 05:26:26

Freq. Stability 40C 3.3V ax80 5290MHz Ant1 0 Minutes




Date: 23.9.2023 05:27:00

Freq. Stability 50C 3.3V ax80 5290MHz Ant1 0 Minutes




Date: 23.9.2023 05:27:34

Freq. Stability 20C 2.81V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:51:42

Freq. Stability 20C 3.3V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:56:37

Freq. Stability 20C 3.80V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:53:07

Freq. Stability -20C 3.3V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:53:48

Freq. Stability -10C 3.3V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:54:31

Freq. Stability 0C 3.3V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:55:13

Freq. Stability 10C 3.3V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:55:35

Freq. Stability 30C 3.3V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:57:19

Freq. Stability 40C 3.3V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:58:01

Freq. Stability 50C 3.3V ax80 5530MHz Ant1 0 Minutes




Date: 20.09.2023 08:58:44

Freq. Stability 20C 2.81V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:18:03

Freq. Stability 20C 3.3V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:22:57

Freq. Stability 20C 3.80V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:19:28

Freq. Stability -20C 3.3V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:20:09

Freq. Stability -10C 3.3V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:20:51

Freq. Stability 0C 3.3V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:21:33

Freq. Stability 10C 3.3V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:22:16

Freq. Stability 30C 3.3V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:23:40

Freq. Stability 40C 3.3V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:24:22

Freq. Stability 50C 3.3V ax80 5610MHz Ant1 0 Minutes




Date: 20.09.2023 09:25:04


Freq. Stability 20C 2.81V ax80 5775MHz Ant1 0 Minutes



Freq. Stability 20C 3.3V ax80 5775MHz Ant1 0 Minutes




Freq. Stability 20C 3.80V ax80 5775MHz Ant1 0 Minutes




Date: 20.09.2023 19:54:02

Freq. Stability -20C 3.3V ax80 5775MHz Ant1 0 Minutes




Date: 20.09.2023 19:54:27


Freq. Stability -10C 3.3V ax80 5775MHz Ant1 0 Minutes



Freq. Stability 0C 3.3V ax80 5775MHz Ant1 0 Minutes




Freq. Stability 10C 3.3V ax80 5775MHz Ant1 0 Minutes




Date: 20.09.2023 19:55:40

Freq. Stability 30C 3.3V ax80 5775MHz Ant1 0 Minutes




Date: 20.09.2023 19:56:28

Freq. Stability 40C 3.3V ax80 5775MHz Ant1 0 Minutes




Date: 20.09.2023 19:56:33

Freq. Stability 50C 3.3V ax80 5775MHz Ant1 0 Minutes




Date: 20.09.2023 19:57:17

Freq. Stability 20C 2.81V ax80 5210MHz Ant2 0 Minutes



Date: 23.09.2023 02:09:45

Freq. Stability 20C 3.3V ax80 5210MHz Ant2 0 Minutes




Date: 23.09.2023 02:13:46

Freq. Stability 20C 3.80V ax80 5210MHz Ant2 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.89 dB RBW 10 kHz
 Att 30 dB SWT 160 ms VBW 30 kHz Mode Sweep
 SGL Count 40/40

1Pk Max



Marker

Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1	1		5.21008 GHz	-25.08 dBm		
M2	1		5.17112 GHz	-28.02 dBm		
M3	1		5.24904 GHz	-29.08 dBm		


Date: 23.SEP.2023 02:10:33

Freq. Stability -20C 3.3V ax80 5210MHz Ant2 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.89 dB RBW 10 kHz
 Att 30 dB SWT 160 ms VBW 30 kHz Mode Sweep
 SGL Count 40/40

1Pk Max




Marker

Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1	1		5.20992 GHz	-26.19 dBm		
M2	1		5.17096 GHz	-28.07 dBm		
M3	1		5.24888 GHz	-27.98 dBm		


Date: 23.SEP.2023 02:11:28

Freq. Stability -10C 3.3V ax80 5210MHz Ant2 0 Minutes




Date: 23.09.2023 02:12:02

Freq. Stability 0C 3.3V ax80 5210MHz Ant2 0 Minutes




Date: 23.09.2023 02:12:37

Freq. Stability 10C 3.3V ax80 5210MHz Ant2 0 Minutes




Date: 23.09.2023 02:13:11

Freq. Stability 30C 3.3V ax80 5210MHz Ant2 0 Minutes




Date: 23.09.2023 02:14:20

Freq. Stability 40C 3.3V ax80 5210MHz Ant2 0 Minutes




Date: 23.09.2023 02:14:34

Freq. Stability 50C 3.3V ax80 5210MHz Ant2 0 Minutes




Date: 23.09.2023 02:15:28

Freq. Stability 20C 2.81V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:19:18

Freq. Stability 20C 3.3V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:23:18

Freq. Stability 20C 3.80V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:20:26

Freq. Stability -20C 3.3V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:21:01

Freq. Stability -10C 3.3V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:21:35

Freq. Stability 0C 3.3V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:22:09

Freq. Stability 10C 3.3V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:22:44

Freq. Stability 30C 3.3V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:23:53

Freq. Stability 40C 3.3V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:24:27

Freq. Stability 50C 3.3V ax80 5290MHz Ant2 0 Minutes




Date: 23.09.2023 02:25:01

Freq. Stability 20C 2.81V ax80 5530MHz Ant2 0 Minutes




Date: 23.09.2023 02:28:12

Freq. Stability 20C 3.3V ax80 5530MHz Ant2 0 Minutes




Date: 23.09.2023 02:32:12

Freq. Stability 20C 3.80V ax80 5530MHz Ant2 0 Minutes




Date: 23.09.2023 02:29:21

Freq. Stability -20C 3.3V ax80 5530MHz Ant2 0 Minutes




Date: 23.09.2023 02:29:55


Freq. Stability -10C 3.3V ax80 5530MHz Ant2 0 Minutes



Freq. Stability 0C 3.3V ax80 5530MHz Ant2 0 Minutes




Freq. Stability 10C 3.3V ax80 5530MHz Ant2 0 Minutes




Date: 23.09.2023 02:31:38

Freq. Stability 30C 3.3V ax80 5530MHz Ant2 0 Minutes




Date: 23.09.2023 02:32:47

Freq. Stability 40C 3.3V ax80 5530MHz Ant2 0 Minutes




Date: 23.9.2023 02:33:21

Freq. Stability 50C 3.3V ax80 5530MHz Ant2 0 Minutes




Date: 23.9.2023 02:33:55

Freq. Stability 20C 2.81V ax80 5610MHz Ant2 0 Minutes




Date: 23.09.2023 02:39:50

Freq. Stability 20C 3.3V ax80 5610MHz Ant2 0 Minutes




Date: 23.09.2023 02:43:50

Freq. Stability 20C 3.80V ax80 5610MHz Ant2 0 Minutes




Date: 23.09.2023 02:40:39

Freq. Stability -20C 3.3V ax80 5610MHz Ant2 0 Minutes




Date: 23.09.2023 02:41:33

Freq. Stability -10C 3.3V ax80 5610MHz Ant2 0 Minutes




Date: 23.09.2023 02:42:07

Freq. Stability 0C 3.3V ax80 5610MHz Ant2 0 Minutes




Date: 23.09.2023 02:42:42

Freq. Stability 10C 3.3V ax80 5610MHz Ant2 0 Minutes




Date: 23.09.2023 02:43:16

Freq. Stability 30C 3.3V ax80 5610MHz Ant2 0 Minutes




Date: 23.09.2023 02:44:25

Freq. Stability 40C 3.3V ax80 5610MHz Ant2 0 Minutes




Date: 23.9.2023 02:44:39

Freq. Stability 50C 3.3V ax80 5610MHz Ant2 0 Minutes




Date: 23.9.2023 02:45:33


Freq. Stability 20C 2.81V ax80 5775MHz Ant2 0 Minutes




Freq. Stability 20C 3.3V ax80 5775MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V ax80 5775MHz Ant2 0 Minutes



Freq. Stability -20C 3.3V ax80 5775MHz Ant2 0 Minutes




Freq. Stability -10C 3.3V ax80 5775MHz Ant2 0 Minutes




Date: 23.09.2023 02:52:18

Freq. Stability 0C 3.3V ax80 5775MHz Ant2 0 Minutes




Date: 23.09.2023 02:52:32

Freq. Stability 10C 3.3V ax80 5775MHz Ant2 0 Minutes




Date: 23.09.2023 02:53:26

Freq. Stability 30C 3.3V ax80 5775MHz Ant2 0 Minutes




Date: 23.09.2023 02:54:35

Freq. Stability 40C 3.3V ax80 5775MHz Ant2 0 Minutes



Date: 23.09.2023 02:55:09

Freq. Stability 50C 3.3V ax80 5775MHz Ant2 0 Minutes



Date: 23.09.2023 02:55:44