



Intertek Testing Services

ETL SEMKO

Report No.: 0103782

Mode: Talk

Tested By: Hong, Report No.: 0103782

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0103782
Mode: Talk

Tested By: Hong, Report No.: 0103782

Scan Settings (1 Range)

[----- Frequencies -----] [----- Receiver Settings -----]

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

27.92500	27.0	48.0
----------	------	------

* limit exceeded