




Error: X-10 RMP File Not Found	SYSTEM X-10 LIMITED		
	Title: 2.4GHz VIDEO SENDER (MINIDin)		
	Number: 851001H11137	Revision: D	
	File Name: A:\MINITX-D.SCH		
	Date: 5-Nov-2002	Drawn By: Ian Wong	Sheet 1 of 1

Error: X-10.BMP File Not Found



OPTION


CAM.

AUD.

AR1HDH0204

EAM/YAM	1800, JUNE 28
EAM	1800, MAY 25
BY	DATE

COMPANY					SYSTEM X-10 LIMITED				
TITLE					MOD				
ADDRESS					851001H11119				
DRAWING NO:		REV		DATE		BY		CHK	
90		A4		SCH.CAMTX1H2		03			
SCALE: 1/2"					SHEET: 1 OF 1				



Title RF BOARD			Protel Technology Inc.	
Size: A4	Number:	Revision:		
File: A:\RF433.SCH	Date: 5-Nov-2002	Time: 16:27:40		

Sheet 1 of 1