

Elizabeth Parish

January 22, 2004

Changes in GMLRH-42

<u>RF</u>

Replace gold plated bronze antenna pins with plain Nickel Silver antenna pins.

BB No Changes

Results of internal review (FCC focus)

FCC tests: RF Power Output, radiated (22.913(a)/24.232(b) Field Strength of Spurious Radiation (2.1053/22) SAR tests required