


Universal Scientific Industrial Co., Ltd.

141, Lane 351, Taiping Road, Sec.1, Tsao Tuen, Nan-Tou, Taiwan

Dear Sirs,

Please be advised the Bluetooth module BM-GP-BR-50 (Broadcom FCC ID: QDS-BRCM1009) is internally set to 0dbm at power setting register. Consumer is not able to access the firmware setting by either application program or OS setting.

Sincerely,



---

David Lee

Product Manager, Bluetooth Module

Product Management Division

Communication BU

Universal Scientific Industrial Co., Ltd.

TEL:886-49-2325876#2174

Email:davidlee@ms.usi.com.tw