






832605

FCC ID: GKRM990
ENCLOSURE





FCC ID: GKRM990
Reference modification letter: No.2



832605

FCC ID: GKRM990



Mechanical construction



832605

FCC ID: GKRM990
Mechanical construction


7



832605

FCC ID: GKR990
Mechanical construction

832605





FCC ID: GKRM990

Reference modification letter: No.3

8326057


CC ID: GKRM990
Mechanical construction






FCC ID: GKRM990
Mechanical construction

11



832605


FCC ID: GKRM990
Mechanical construction




832605


FCC ID: GKRM990
Mechanical construction

832605






832605




FCC ID: GKRM990
Mechanical construction



832605

FCC ID: GKRM990

Front side of CRT board




832605


FCC ID: GKRM990
Rears side of CRT board
Reference modification letter: No.4,5

832605

FCC ID: GKRM990
Reference modification letter: No.6





832605



FCC ID: GKRM990
Mechanical construction


832605



FCC ID: GKRM990

Mechanical construction


832605



FCC ID: GKRM990

Front side of Single cable board


832605




FCC ID: GKRM990

Rear side of single cable board

Reference modification letter: No.7,8




FCC ID: GKRM990
Reference modification letter: No.9




FCC ID: GKRM990

Mechanical construction



832605

FCC ID: GKRM990
Front side of main board



832605

FCC ID: GKRM990

Rear side of main board

Reference modification letter No.

10, 11, 12, 13