



Lat-Lon LLC, A Geotab Company
2300 South Jason St.
Denver, CO 80223, USA

FEB 01, 2022

Subject: Declaration of MX5000 CATM RevH HW Changes

By means of this letter, **Lat-Lon LLC.** declares that the Lat-Lon MX5000_4GPLUS_RevH Revision **H**, has the following hardware component changes for the purpose of PTCRB/FCC/ISED review:

Component Designator	Reason for Change
FID1, FID2, FID3	Added 3 fiducials on top layer.
FID4, FID5, FID6	Added 3 fiducials on bottom layer
StaicVia39, StaicVia44, StaicVia45	Moved 3 vias for distances less than 1.5mm to allow space for FID6 fiducial on the bottom layer
NET72	Moved the trace of net (2.5/3.3V Interface voltage Selection) around the FID1 location on the top layer .
~RESET	Moved 5mm section of Trace of the Net ~RESET for 1 millimeter to allow space for FID1 fiducial on the top layer.

Sincerely,

[Joe Deppong](#)

Senior Hardware Engineer