


INTERTEK TESTING SERVICE

Report No.: 17091178HKG-003 (FCC)
17091178HKG-004 (IC)

Equipment Photographs

Model : 52127TXH

(Internal)



FCC ID: PQN52127TXH2G4
IC: 4438B-52127TXH


INTERTEK TESTING SERVICE

Report No.: 17091178HKG-003 (FCC)
17091178HKG-004 (IC)

Equipment Photographs

Model : 52127TXH

(Internal)



FCC ID: PQN52127TXH2G4
IC: 4438B-52127TXH



INTERTEK TESTING SERVICE

Report No.: 17091178HKG-003 (FCC)
17091178HKG-004 (IC)

Equipment Photographs

Model : 52127TXH

(Internal)



FCC ID: PQN52127TXH2G4
IC: 4438B-52127TXH



INTERTEK TESTING SERVICE

Report No.: 17091178HKG-003 (FCC)
17091178HKG-004 (IC)

Equipment Photographs

Model : 52127TXH

(Internal)



FCC ID: PQN52127TXH2G4
IC: 4438B-52127TXH



INTERTEK TESTING SERVICE

Report No.: 17091178HKG-003 (FCC)
17091178HKG-004 (IC)

Equipment Photographs

Model : 52127TXH

(Internal)



FCC ID: PQN52127TXH2G4
IC: 4438B-52127TXH


INTERTEK TESTING SERVICE

Report No.: 17091178HKG-003 (FCC)
17091178HKG-004 (IC)

Equipment Photographs

Model : 52127TXH

(Internal)



FCC ID: PQN52127TXH2G4
IC: 4438B-52127TXH