APPLICANT: MOTOROLA SOLUTIONS EQUIPMENT TYPE: ABZ89FT5912

109AB-T5912


# **Photographs of the Device**

Photographs – Index

EXHIBIT	DESCRIPTION
A1	ID Label Location
A2	FCC / IC Identification Label

# **Photographs of the Device**

ID Label Location



**EQUIPMENT TYPE: ABZ89FT5912** 109AB-T5912

#### **Photographs of the Device**

FCC / IC Identification Label





### **D-Series**

### Multicarrier Radio Site

Model No: T8899A Serial No: 675CAM003

F.O. CPQ3 - 2033 -82332

Page No: 1 item No: 1

FCC ID: ABZ89FT5912

IC:109AB-T5912 HVIN:T8899-700H







Super Model:SQM01SUM0338A Serial No: 675CAM0004

This device complies with Part 15 of the FCC rules. Operation is subject of the following two conditions: (1) This device may not be harmful interference and (2) this device must accept any interference received including interference that may cause undersired operation.

> Mfg. Date: MM/DD/YYYY Made in Mexico 48.0 V === 65A X2 Max