
Report No.: FR551807

Appendix C. Set up Photograph

Conducted Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C3
Report Issued Date : Jun. 09, 2005



SIDE VIEW


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C3
Report Issued Date : Jun. 09, 2005



Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C3
Report Issued Date : Jun. 09, 2005