

Report No.: CTA23062501001 Page 31 of 41

Band-edge Measurements for RF Conducted Emissions:







Report No.: CTA23062501001 Page 32 of 41

4.7 Antenna Requirement

Standard Applicable

For intentional device, according to RSS-Gen 6.8:

An intentional radiator shall be designed to ensure that no antenna other than that furnished by the responsible party shall be used with the device. The use of a permanently attached antenna or of an antenna that uses a unique coupling to the intentional radiator, the manufacturer may design the unit so that a broken antenna can be replaced by the user, but the use of a standard antenna jack or electrical connector is prohibited

For intentional device, according to FCC 47 CFR Section 15.203:

An intentional radiator shall be designed to ensure that no antenna other than that furnished by the responsible party shall be used with the device. The use of a permanently attached antenna or of an antenna that uses a unique coupling to the intentional radiator, the manufacturer may design the unit so that a broken antenna can be replaced by the user, but the use of a standard antenna jack or electrical connector is prohibited

FCC CFR Title 47 Part 15 Subpart C Section 15.247(c) (1) (I):

(i) Systems operating in the 2400-2483.5 MHz band that is used exclusively for fixed. Point-to-point operations may employ transmitting antennas with directional gain greater than 6dBi provided the maximum conducted output power of the intentional radiator is reduced by 1 dB for every 3 dB that the directional gain of the antenna exceeds 6dBi.

Test Result:

The maximum gain of antenna was 1.90 dBi.

Remark: The antenna gain is provided by the customer, if the data provided by the customer is not accurate, Shenzhen CTA Testing Technology Co., Ltd. does not assume any responsibility.




Report No.: CTA23062501001 Page 33 of 41

5 Test Setup Photos of the EUT







Report No.: CTA23062501001 Page 34 of 41


6 Photos of the EUT








Report No.: CTA23062501001 Page 35 of 41









Report No.: CTA23062501001 Page 36 of 41








Report No.: CTA23062501001 Page 37 of 41







Report No.: CTA23062501001 Page 38 of 41








Report No.: CTA23062501001 Page 39 of 41







Report No.: CTA23062501001 Page 40 of 41







Page 41 of 41 Report No.: CTA23062501001

