


Page 6 / 25

Report No.: T190902N03 Rev. 00


## Internal Photo (Model: MPC LIVE )







Page 7 / 25 **Report No.:** T190902N03 Rev. 00









Page 8 / 25

Report No.: T190902N03 Rev. 00









 Report No.:
 T190902N03

 Page
 9 / 25


 Rev.
 00









Page 10 / 25 **Report No.:** T190902N03 Rev. 00









Page 11 / 25 **Report No.:** T190902N03 Rev. 00








Page 12 / 25 **Report No.:** T190902N03 Rev. 00









Page 13 / 25

Report No.: T190902N03 Rev. 00









Page 14 / 25


Report No.: T190902N03 Rev. 00









Page 15 / 25 Report No.: T190902N03 Rev. 00








Page 16 / 25 Report No.: T190902N03 Rev. 00









Page 17 / 25

Report No.: T190902N03 Rev. 00









Page 18 / 25

Report No.: T190902N03 Rev. 00








Page 19 / 25 **Report No.:** T190902N03 Rev. 00








Page 20 / 25 **Report No.:** T190902N03 Rev. 00








Page 21 / 25

Report No.: T190902N03 Rev. 00








Page 22 / 25 **Report No.:** T190902N03 Rev. 00









 Report No.:
 T190902N03

 Page
 23 / 25

 Rev.
 00








Page 24 / 25

Report No.: T190902N03 Rev. 00







Page 25 / 25 **Report No.:** T190902N03 Rev. 00

