

FCC ID Label Location

The product does not have enough space to place the label, and FCC ID label is reflected in the user manual and package, as below:

User Manual:

User Manual.pdf - Adobe Acrobat Pro DC
文件(F) 编辑(E) 视图(V) 窗口(W) 帮助(H)
主页 工具 文档 1 / 1 150%
IFB,
FB for about 2 seconds.
B
B on the left earphone
n the right earphone for
e phone, press the MFB
the voice assistant.
nd not connected to
ton of one earphone five

Indicator/Voice Prompt Guide

Mode	Description	Voice Prompt
Power On	-	"Power On"
Power Off	-	"Power Off"
Pairing	-	"Pairing"
Connected	-	"Connected"
Charging case	When charging the charging case, the indicator light on the charging case flashes, and it will stay on after being fully charged	-

Cautions

- After removing the earphones from the charging case, without pressing any buttons, the left and right earpieces will connect automatically. When no connections found, it will enter automatic pairing mode.
- Please place the earphones in the correct location (L/R) for normal charging.
- Replacement of battery (on your own) is not recommended.
- Do not expose battery (battery pack) to excessive heat such as direct sunlight or fire.

FCC Warning

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Any Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Note: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

The device has been evaluated to meet general RF exposure requirement. The device can be used in portable exposure condition without restriction.

FCC ID: 2AVD2-MH22163

Package:

MONSTER
N-LITE 203 AIRLINKS
Wireless Earbuds

FCC ID: 2AVD2-MH22163

ROOM 1002, Building A, Fencheng Zhigao Building,
60 Tiezai Road, Xixiang Street, Bao'an District,
Shenzhen, China.

Monster Bluetooth Headphones
Model No.: MH22163
FCC ID: 2AVD2-MH22163

Hereby, Shenzhen Monster Creative Technology Co., Ltd.
wireless device is in compliance with requirement
Directive 2014/53/EU.

