

From: amanda@adt.com.tw [mailto:amanda@adt.com.tw]
Sent: Thursday, April 27, 2006 3:07 AM
To: steve.cheng
Cc: eric@adt.com.tw; may@adt.com.tw; Ken_Lu@adt.com.tw
Subject: Done! : TCB Review Comments for (B06-0426c- Q87-WRT300NV1,950420H02- Cisco 11n Router)

Dear Steve,

Please see response below.
Thanks!

Best Regards,

Amanda Chu / 朱芳誼 

Certification Specialist / ADT Corp. (Hsin Chu Office)

Tel: 03-5935343 ext. 1737 Fax: 03-5934728

"steve.cheng" <steve.cheng@nacsemc.com>

2006/04/27 上午 11:44

收件人 amanda@adt.com.tw

副本抄

送

主旨 TCB Review Comments for (B06-0426c- Q87-WRT300NV1,950420H02- Cisco 11n Router)


TCB Review Comments for (B06-0426c- Q87-WRT300NV1, 950420H02- Cisco 11n Router)

-EMC-

Question #1: P 136 or test report Sweep Time setting is wrong please re-take data.

=> Plot has been re-measured with correct setting and test report updated.

CH7



Question #2: Is this product a 2x2 MIMO or 2x3 MIMO? Does this product capable of 1x2 or other configuration? Please conform.

=>This device support only 2x2 MIMO as tested in the report; all other functions are not available for this version.

Best regards,

Steve Cheng
Curtis Straus LLC