

AzureWave Technologies, Inc.

8F., No.94, Baozhong Rd., Xindian Dist., New Taipei City 23144, Taiwan TEL: +886-2-55995599 FAX: +886-2-66289666

DFS client device channel plan and software operational declaration

Date: 2019-07-23 FCC ID: TLZ-CM382

We, <u>AzureWave Technologies</u>, <u>Inc.</u>, declare that the device, FCC ID: TLZ-CM382 Model Name: AW-CM382, does not have Ad Hoc on "non-US frequencies" and/or on" DFS frequencies". Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

Below is the channel / frequency plan for the device

2.4G

СН	1	2	3	4	5	6	7	8	9	10	11
Frequency (MHz)	2412	2417	2422	2427	2432	2437	2442	2447	2452	2457	2462
Scan Type	Active										

5G Band 1

СН	36	38	40	42	44	46	48
Frequency (MHz)	5180	5190	5200	5210	5220	5230	5240
Scan Type	Active						

5G Band 2

СН	52	54	56	58	60	62	64
Frequency (MHz)	5260	5270	5280	5290	5300	5310	5320
Scan Type	Passive						

5G Band 3

СН	100	102	104	106	108	110	112	116	118	120	122
Frequency (MHz)	5500	5510	5520	5530	5540	5550	5560	5580	5590	5600	5610
Scan Type	Passive										
СН	124	126	128	132	134	136	140		•		•
Frequency (MHz)	5620	5630	5640	5660	5670	5680	5700				
Scan Type	Passive										

5G Band 4

СН	149	151	153	155	157	159	161	165
Frequency (MHz)	5745	5755	5765	5775	5785	5795	5805	5825
Scan Type	Active							

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by a special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before



AzureWave Technologies, Inc.

8F., No.94, Baozhong Rd., Xindian Dist., New Taipei City 23144, Taiwan TEL: +886-2-55995599 FAX: +886-2-66289666

firmware upgrade. Unauthorized modification to firmware will lead to the failure of verification and thus firmware upgrade will not be allowed. Sincerely yours,

Patrick Lin / Director

AzureWave Technologies, Inc.

Tel: 02-55995599 *5580

Fax: 02-66289666

E-mail: patrick.lin@azurewave.com