

6660-B Dobbin Road Columbia, MD 21045 USA

Tel. 410.290.6652 Fax. 410.290.6654 http://www.pctestlab.com

May 10, 2004

Federal Communications Commission Equipment Approval Services 7435 Oakland Mills Road Columbia, MD 21046 Attn: Mr. Martin Perrine

> SUBJECT: Motorola, Inc. FCC ID: ABZ89FT7606 731 Confirmation No.: TC754291 Correspondence Reference No.: 12054 Request for Tech. Info.: 04/16/04

Dear Tim:

Transmitted herewith, on behalf of **Motorola Inc.** is the answer to question #3 in response to the request for technical information dated April 14, 2004. Please find all other answers in Motorola's Cover Letter.

1. To comply with Oct02 TCB Q/A Feb04 TCB training notes, the unit was tested with both simultaneous and single transmission and the worst case data was reported

We trust this information is sufficient to resolve FCC questions in this application. If you have any further questions, please do not hesitate to contact us.

Randy Ortanez President

cc: Samsung Electronics Co., Ltd.