

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


Worst Case Position

Below 1GHz **Horizontal: X-axis / Vertical: X-axis**
Above 1GHz: **Horizontal: X-axis / Vertical: Z-axis**


X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1

End of Report