
	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHT181LW (STV100-2)			Page 1(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-October 30, 2015	Report No RTS-6066-1511-06	FCC ID L6ARHT180LW	

Annex E: Test set up photos

	Document			Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHT181LW (STV100-2)			2(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-October 30, 2015	Report No RTS-6066-1511-06	FCC ID L6ARHT180LW	

Telecoil (0, 15 mm)

Audio Output (0, 0)





Figure E1. BlackBerry Smartphone, Slider Closed

	Document			Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHT181LW (STV100-2)			3(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-October 30, 2015	Report No RTS-6066-1511-06	FCC ID L6ARHT180LW	

Telecoil (0, 15 mm)

Audio Output (0, 0)





Figure E2. BlackBerry Smartphone, Slider Open

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHT181LW (STV100-2)		Page 4(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-October 30, 2015	Report No RTS-6066-1511-06	FCC ID L6ARHT180LW






Figure E3: Ambient noise and system validation measurement setup

	Document		Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHT181LW (STV100-2)		5(5)
Author Data Daoud Attayi	Dates of Test Sep. 02-October 30, 2015	Report No RTS-6066-1511-06	FCC ID L6ARHT180LW





Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup