

Page : 1 of 4 Issued date : 2021/7/20 FCC ID : JNZA00150

Radiated Spurious Emission Setup Configurations

Above 1GHz






Underwriters Laboratories Taiwan Co., Ltd.Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948



Page : 2 of 4 Issued date : 2021/7/20 FCC ID : JNZA00150

Below 1GHz





Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000
Facsimile (FAX) :+886-3-583-7948



Page : 3 of 4 Issued date : 2021/7/20 FCC ID : JNZA00150

Below 30MHz





Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Page : 4 of 4 Issued date : 2021/7/20 FCC ID : JNZA00150

AC Power Line Conducted Emission Setup Configurations





Telephone Facsimile (FAX) :+886-3-583-7948