





Report No.: TMWK2309003309KR

Page: 84 / 757
Rev.: 00


802.11n 40MHz Chain0 5190MHz




802.11n 40MHz Chain0 5310MHz




802.11n 40MHz Chain0 5230MHz




802.11n 40MHz Chain0 5510MHz



802.11n 40MHz Chain0 5270MHz



802.11n 40MHz Chain0 5550MHz







Report No.: TMWK2309003309KR

Page: 85 / 757
Rev.: 00


802.11n 40MHz Chain0 5670MHz




802.11n 40MHz Chain1 5190MHz




802.11n 40MHz Chain0 5755MHz




802.11n 40MHz Chain1 5230MHz



802.11n 40MHz Chain0 5795MHz



802.11n 40MHz Chain1 5270MHz






Report No.: TMWK2309003309KR

Page: 86 / 757
Rev.: 00


802.11n 40MHz Chain1 5310MHz




802.11n 40MHz Chain1 5670MHz




802.11n 40MHz Chain1 5510MHz




802.11n 40MHz Chain1 5755MHz



802.11n 40MHz Chain1 5550MHz






802.11n 40MHz Chain1 5795MHz





Report No.: TMWK2309003309KR




Page: 87 / 757
Rev.: 00






Report No.: TMWK2309003309KR

Page: 88 / 757
Rev.: 00




Report No.: TMWK2309003309KR


802.11ac 160MHz Chain0 5250MHz




802.11ac 160MHz Chain1 5250MHz



802.11ac 160MHz Chain0 5570MHz








802.11ac 160MHz Chain1 5570MHz





Report No.: TMWK2309003309KR







Page: 90 / 757
Rev.: 00





Report No.: TMWK2309003309KR







Page: 91 / 757
Rev.: 00





Report No.: TMWK2309003309KR







Page: 92 / 757
Rev.: 00





Report No.: TMWK2309003309KR






Page: 93 / 757
Rev.: 00





Report No.: TMWK2309003309KR

Page: 94 / 757
Rev.: 00





Report No.: TMWK2309003309KR

Page: 95 / 757
Rev.: 00

