



Photographs of the Device

*Internal Front View – Transceiver Module Circuit Board Top View*



Photographs of the Device


*Internal Front View – Transceiver Module, Control Section*






Photographs of the Device

*Internal Front View – Transceiver Module, Exciter Section*



Photographs of the Device


*Internal Front View – Transceiver Module, Receiver Section*





Photographs of the Device

*Internal Front View – Power Amplifier Module, Cover Removed*




Photographs of the Device

*Internal Front View – Power Supply Module*



Photographs of the Device

*Internal Front View – Power Supply Module, Circuit Boards, Top View*






APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC4819

Photographs of the Device


*Internal Front View – Backplane*





Photographs of the Device

*Internal Back View – Transceiver Module*



Photographs of the Device

*Internal Back View – Power Amplifier Module*





Photographs of the Device

*Internal Back View – Power Supply Module, Circuit Boards, Back View*



APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC4819

Photographs of the Device

*Internal Back View – Backplane*

