

n77_2_80MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB217@0 77.179MHz




n77_2_80MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB217@0 77.451MHz



n77_2_80MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB217@0 77.441MHz



n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB243@0 86.534MHz




n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 86.541MHz




n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB243@0 86.459MHz




n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB243@0 86.766MHz




n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB243@0 86.777MHz



n77_2_90MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB245@0 87.191MHz




n77_2_90MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB245@0 87.290MHz




n77_2_90MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB245@0 87.212MHz




n77_2_90MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB245@0 87.190MHz




n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB270@0 96.504MHz




n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 96.122MHz




n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB270@0 96.091MHz



n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB270@0 96.171MHz




n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB270@0 96.071MHz




n77_2_100MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB273@0 97.236MHz



n77_2_100MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB273@0 96.974MHz




n77_2_100MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB273@0 97.263MHz




n78_2


n77_2_100MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB273@0 96.964MHz




n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB24@0 8.568MHz




n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB24@0 8.572MHz




n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB24@0 8.578MHz




n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB24@0 8.578MHz




n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB24@0 8.563MHz




n78_2_10MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB24@0 8.573MHz




n78_2_10MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB24@0 8.572MHz




n78_2_10MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB24@0 8.570MHz




n78_2_10MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB24@0 8.616MHz




n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.453MHz




n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB36@0 13.448MHz



n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB36@0 13.518MHz



n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB36@0 13.457MHz



n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB36@0 13.463MHz



n78_2_15MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB38@0 13.566MHz

