



n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 -47.57dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:29:41

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -45.78dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 09:24:11

n77_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@188 -46.19dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 09:25:09

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB180@0 -47.39dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:32:33

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@0 -47.22dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:30:46

n77_2_70MHz_30kHz_3665MHz_DFT-s-OFDM
QPSK_RB1@188 -46.88dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:31:40

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@0 -47.58dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:33:38

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB1@216 -44.58dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:34:33

n77_2_80MHz_30kHz_3590MHz_DFT-s-OFDM
QPSK_RB216@0 -47.34dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:35:26

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.47dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:36:26

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@216 -46.96dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:37:20

n77_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 -47.68dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:38:13

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@0 -47.03dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:39:13

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB1@216 -47.52dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:40:08

n77_2_80MHz_30kHz_3660MHz_DFT-s-OFDM
QPSK_RB216@0 -47.36dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:41:01

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@0 -46.50dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:42:03

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB1@244 -45.98dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:42:59

n77_2_90MHz_30kHz_3595MHz_DFT-s-OFDM
QPSK_RB243@0 -47.67dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 10:43:52

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.65dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:43:26

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@244 -46.11dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:44:22

n77_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 -46.63dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:45:18

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@0 -47.26dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:46:21

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB1@244 -45.22dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:47:18

n77_2_90MHz_30kHz_3655MHz_DFT-s-OFDM
QPSK_RB243@0 -47.21dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:48:13

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@0 -44.14dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:49:18

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB1@272 -44.03dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:50:15

n77_2_100MHz_30kHz_3600MHz_DFT-s-OFDM
QPSK_RB270@0 -47.59dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:51:10

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.13dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:52:11

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@272 -47.80dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:53:09

n77_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 -47.24dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 9.DEC.2024 12:54:03


n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@0 -44.55dBm




n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB1@272 -47.39dBm




n77_2_100MHz_30kHz_3650MHz_DFT-s-OFDM
QPSK_RB270@0 -47.36dBm




n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB1@0 -47.03dBm




n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB1@23 -47.51dBm



n78_2_10MHz_30kHz_3555MHz_DFT-s-OFDM
QPSK_RB24@0 -47.51dBm




n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.12dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 02:54:31

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@23 -47.47dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 02:55:45

n78_2_10MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB24@0 -47.53dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 02:56:58

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB1@0 -47.19dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 02:58:17

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB1@23 -46.91dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 02:59:31

n78_2_10MHz_30kHz_3695MHz_DFT-s-OFDM
QPSK_RB24@0 -47.59dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 03:00:45

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@0 -47.62dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 17:47:21

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB1@37 -47.10dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 17:48:18

n78_2_15MHz_30kHz_3557.5MHz_DFT-s-OFDM
QPSK_RB36@0 -47.54dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 17:49:15

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.75dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 17:50:17

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@37 -47.68dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 17:51:15

n78_2_15MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB36@0 -47.35dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 10.DEC.2024 17:52:11

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@0 -46.96dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:13:12

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB1@37 -47.18dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:14:08

n78_2_15MHz_30kHz_3692.5MHz_DFT-s-OFDM
QPSK_RB36@0 -47.06dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:15:04

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB1@0 -47.22dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:25:16

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB1@50 -47.37dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:26:13

n78_2_20MHz_30kHz_3560MHz_DFT-s-OFDM
QPSK_RB50@0 -47.61dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:27:09

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -47.29dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:28:11

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@50 -47.88dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:29:08

n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB50@0 -47.12dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:30:04

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB1@0 -47.73dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:31:06

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB1@50 -47.40dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:32:03

n78_2_20MHz_30kHz_3690MHz_DFT-s-OFDM
QPSK_RB50@0 -47.94dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:33:07

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB1@0 -47.81dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:34:13

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB1@77 -46.81dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:35:11

n78_2_30MHz_30kHz_3565MHz_DFT-s-OFDM
QPSK_RB75@0 -47.19dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:36:07

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@0 -46.99dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:37:12

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB1@77 -47.60dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:38:11

n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB75@0 -47.05dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 11.DEC.2024 10:39:09