

350 East Plumeria Drive San Jose California, United States 95134  
TEL: 408-89-3657 FAX: 408-907-8097

Date: 2017-06-19

Below is the channel / frequency plan for the device

[illegible]

# Netgear Incorporated

350 East Plumeria Drive San Jose California, United States 95134

TEL: 408-89-3657 FAX: 408-907-8097

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode, on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before firmware upgrade. Unauthorized modification to firmware will lead the failure of verification thus firmware upgrade is not allowed.

Sincerely yours,



-----  
David Kay / Regulatory Compliance Manager

Tel: 4088903657

Fax: 4089078097

E-mail: david.kay@netgear.com