

Continental Automotive Systems Corporation

45-29, Saeum-ro, Icheon-si, Gyeonggi-Do, 467-080, Korea

T. 82-31-645-4864, F. 82-31-637-0371

Date: August 3, 2018

To: UL Verification Services Inc. (formerly UL CCS)

47173 Benicia Street, Fremont, CA 94538 Phone: (510) 771-1000, FAX: (510) 661-0888

Dear Sir/Madam,

Label is placed in the battery compartment due to below reason:

The label placed on the exterior of the equipment affect the appearance according to design requirements because it would be easily removed and limited space of label area.

Therefore, the label is placed on the battery compartment and on the user manual.

Sincerely Yours,

Sung-Min Jang

/ Representative

/Continental Automotive Systems Corporation