

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

(Horizontal: X0-axis / Vertical: Z0-axis) (Below 1 GHz)
(Horizontal: Y90-axis / Vertical: Z0-axis) (Above 1 GHz)

X0-axis



X90-axis



Y0-axis



Y90-axis



Z0-axis



Z90-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124