


Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 1
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 2
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 3
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 4
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 5
FCC ID: P3—LP9100




Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 6
FCC ID: P3—LP9100




Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 7
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 8
FCC ID: P3—LP9100




Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 9
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 10
FCC ID: P3—LP9100





Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 12
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 13
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 14
FCC ID: P3—LP9100



Annex 3 - Internal Photographs of EUT
Mobile Payment Terminal, Model LP9100, K78-204

Photo # 15
FCC ID: P3—LP9100

