



FCC Test Setup Photos

FCC Part 15.247 for FHSS systems/ CANADA RSS-210

FOR:

JACK SERVICE POINT

MODEL #: SP640

**WIDERAY CORPORATION
25 KEARNY STREET—6TH FLOOR
SAN FRANCISCO, CALIFORNIA 94108
U.S.A**

FCC ID: SONSP640TY

IC ID: 5509A-SP640TY

**REFERENCE TEST REPORT #: EMC_1040_2005_BLUETOOTH
DATE: SEPTEMBER 20, 2005**



TTI-P-G 081/94-A0

Accredited according to **ISO/IEC 17025**



FCC listed # 101450

IC recognized # 3925

CETECOM Inc.

411 Dixon Landing Road • Milpitas, CA 95035 • U.S.A.

Phone: + 1 (408) 586 6200 • Fax: + 1 (408) 586 6299 • E-mail: info@cetecomusa.com • <http://www.cetecom.com>

CETECOM Inc. is a Delaware Corporation with Corporation number: 2113686

Board of Directors: Dr. Harald Ansorge, Dr. Klaus Matkey, Hans Peter May

© Copyright by CETECOM

Table of Contents


1	ASSESSMENT	3
2	TEST SETUP PHOTOS	4

1 Assessment

The following is in compliance with the applicable criteria specified in FCC rules Part 15.247 of the Code of Federal Regulations and in compliance with the applicable criteria specified in Industry Canada rules RSS210.

Company	Description	Model #
WIDERAY CORP.	JACK SERVICE POINT	SP640

2 TEST SETUP PHOTOS




RADIATED EMISSIONS




<CLOSE UP> RADIATED EMISSIONS



AC LINE CONDUCTION



AC LINE CONDUCTION



ANTENNA PORT CONDUCTED MEASUREMENT