

Appendix C. Set up Photograph

Conducted Emission



Report No.: FR500501

FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C5
Report Issued Date : Oct. 17, 2005
FCC ID : HFS-Atom
Report Version : Rev. 01






SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C5
Report Issued Date : Oct. 17, 2005
FCC ID : HFS-Atom
Report Version : Rev. 01



Conducted Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C5
Report Issued Date : Oct. 17, 2005
FCC ID : HFS-Atom
Report Version : Rev. 01





SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C5

Report Issued Date : Oct. 17, 2005


FCC ID : HFS-Atom

Report Version : Rev. 01






Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C5 of C5
Report Issued Date : Oct. 17, 2005
FCC ID : HFS-Atom
Report Version : Rev. 01